	Versa Note	2015	o put all promises in writing. Keep this form.
Nissan Vehicle make		YEAR	3N1CE2CP7FL375644 VEHICLE IDENTIFICATION NUMBER (VIN)
	FOR THIS VEHICLE:		
	S - NO DE	ALER V	VARRANTY
THE DEALE	R DOES NOT PROVIDE A WA	RRANTY FOR ANY	(REPAIRS AFTER SALE.
	LER WAR	RANTY	(
that fail durir explain warr	ng the warranty period. Ask the	dealer for a copy o	nd <u>100</u> % of the parts for the covered systems of the warranty, and for any documents that obligations. <i>Implied warranties</i> under your
SYSTEMS COVERE	D:	DURATIO	N:
ENGINE		1,000 miles	
TRANSMISSION		1,000 mile	es
POWER STEERING		1,000 miles	
AIR CONDITIONI	NG	1,000 mile	es
Wearable parts such as brak	es, tires, or alignments ARE NOT Warran	tied	
NON-DEALER V	VARRANTIES FOR TH	IS VEHICLE:	:
MANUFACTURE		S. The manufactur	rer's original warranty has not expired on some
MANUFACTURE	R'S USED VEHICLE WARRAN	TY APPLIES.	
OTHER USED VE	EHICLE WARRANTY APPLIES.		
Ask the dealer for a cooligations.	opy of the warranty document a	nd an explanation o	f warranty coverage, exclusions, and repair
coverage, deduct		u buy a service cor	e for an extra charge. Ask for details about ntract within 90 days of your purchase of this itional rights.
ASK THE DEALER	IF YOUR MECHANIC CAN IN	SPECT THE VEH	ICLE ON OR OFF THE LOT.
how to obtain a vehic	cle history report, visit ftc.gov/u	usedcars. To chec	SAFETY RECALLS. For information on k for open safety recalls, visit safercar.gov. make the best use of the resources on
SEE OTHER SIDE f	or important additional infor	mation, including	g a list of major defects that may occur in
used motor vehicle			,,,,

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator Improperly functioning water pump

Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags**

Steering System

Too much free play at steering wheel (DOT specs.) Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning improperly

Tires

Tread depth less than 2/32 inch Sizes mismatched

Visible damage

- Wheels
- Visible cracks, damage or repairs Mounting bolts loose or missing

Exhaust System

Leakage Catalytic Converter

DEALER NAME

<u>Chacon Autos, Ltd.</u>

1400 SE. Military Dr, San Antonio, TX 78214

TELEPHONE

chaconinfo@chaconautos.com

210-922-4000 FOR COMPLAINTS AFTER SALE, CONTACT:

Contact service department at 210-922-4000

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).