IMPORTANT: Spoken promises are difficult to		
Mercedes-Benz C-Class	2008	WDDGF54X78R019403
VEHICLE MAKE MODEL		VEHICLE IDENTIFICATION NUMBER (VIN)
WARRANTIES FOR THIS VEHIC	JLC.	
THE DEALER DOES NOT PROVIDE		
	RRANT	Y
FULL WARRANTY.		
that fail during the warranty period.	Ask the dealer for a copy is, and the dealer's repair	and <u>100</u> % of the parts for the covered systems of the warranty, and for any documents that obligations. <i>Implied warranties</i> under your
SYSTEMS COVERED:	DURATIC	DN:
ENGINE	1,000 mi	les
TRANSMISSION	1,000 mi	les
POWER STEERING	1,000 mi	les
AIR CONDITIONING	1,000 mi	les
Wearable parts such as brakes, tires, or alignments ARE NC	T Warrantied	
NON-DEALER WARRANTIES FO	R THIS VEHICLE	:
MANUFACTURER'S WARRANTY STILL, components of the vehicle.	APPLIES. The manufactu	irer's original warranty has not expired on some
MANUFACTURER'S USED VEHICLE WA	RRANTY APPLIES.	
OTHER USED VEHICLE WARRANTY AP	PLIES.	
Ask the dealer for a copy of the warranty docu obligations.	ment and an explanation	of warranty coverage, exclusions, and repair
	s. If you buy a service co	ble for an extra charge. Ask for details about ntract within 90 days of your purchase of this ditional rights.
ASK THE DEALER IF YOUR MECHANIC	CAN INSPECT THE VEH	
<b>OBTAIN A VEHICLE HISTORY REPORT A</b> how to obtain a vehicle history report, visit fi You will need the vehicle identification numb	ND CHECK FOR OPEN tc.gov/usedcars. To chec	SAFETY RECALLS. For information on ck for open safety recalls, visit safercar.gov.
these sites.		g a list of major defects that may occur in

Here is a list of some major defects that may occur in used vehicles.

#### Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

#### Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

#### Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

#### Cooling System

Leakage including radiator Improperly functioning water pump

#### Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

#### Fuel System

## Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

#### Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags** 

#### Steering System

Too much free play at steering wheel (DOT specs.) Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

#### Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning improperly

#### Tires

Tread depth less than 2/32 inch Sizes mismatched

#### Visible damage

- Wheels
- Visible cracks, damage or repairs Mounting bolts loose or missing

#### Exhaust System

Leakage Catalytic Converter

## DEALER NAME

<u>Chacon Autos, Ltd.</u>

# 1400 SE. Military Dr, San Antonio, TX 78214

TELEPHONE

## chaconinfo@chaconautos.com

210-922-4000 FOR COMPLAINTS AFTER SALE, CONTACT:

# Contact service department at 210-922-4000

**IMPORTANT:** The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).