		lealer to put all promises in writing. Keep this form.
	Impala Limited 2015	2G1WB5E32F1124619
		VEHICLE IDENTIFICATION NUMBER (VIN)
		R WARRANTY
	ES NOT PROVIDE A WARRANTY FO	
	ER WARRAN	ТҮ
FULL WARRANTY		
that fail during the explain warranty co	warranty period. Ask the dealer for a	abor and <u>100</u> % of the parts for the covered systems copy of the warranty, and for any documents that repair obligations. <i>Implied warranties</i> under your
SYSTEMS COVERED:	DUF	RATION:
ENGINE	1,00	00 miles
TRANSMISSION	1,00	00 miles
POWER STEERING	1,00	00 miles
AIR CONDITIONING	1,00	00 miles
Wearable parts such as brakes, tires,	or alignments ARE NOT Warrantied	
NON-DEALER WAR	RANTIES FOR THIS VEHI	CLE:
MANUFACTURER'S WA		ufacturer's original warranty has not expired on some
	ED VEHICLE WARRANTY APPLIES	
OTHER USED VEHICLE	WARRANTY APPLIES.	
Ask the dealer for a copy of biligations.	he warranty document and an explan	ation of warranty coverage, exclusions, and repair
coverage, deductible, pr		vailable for an extra charge. Ask for details about ice contract within 90 days of your purchase of this ou additional rights.
ASK THE DEALER IF YOU	IR MECHANIC CAN INSPECT TH	E VEHICLE ON OR OFF THE LOT.
OBTAIN A VEHICLE HIST how to obtain a vehicle hist	ORY REPORT AND CHECK FOR ( ory report, visit ftc.gov/usedcars. To	<b>DPEN SAFETY RECALLS.</b> For information on to check for open safety recalls, visit safercar.gov. ove to make the best use of the resources on
	ortant additional information, inc	luding a list of major defects that may occur in
used motor vehicles.		

Here is a list of some major defects that may occur in used vehicles.

#### Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

#### Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

### Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

#### Cooling System

Leakage including radiator Improperly functioning water pump

#### Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

#### Fuel System

## Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

### Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags** 

# (DOT specs.)

Steering System

Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

Too much free play at steering wheel

### Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning

#### Tires

Tread depth less than 2/32 inch Sizes mismatched

#### Visible damage

improperly

Wheels

Visible cracks, damage or repairs Mounting bolts loose or missing

### Exhaust System

Leakage Catalytic Converter

## DEALER NAME

<u>Chacon Autos, Ltd.</u>

# 3315 E Pioneer Pkwy, Arlington, TX 76010

TELEPHONE

chaconinfo@chaconautos.com

## 214-826-6000 FOR COMPLAINTS AFTER SALE, CONTACT:

# Contact service department at 214-826-6000

**IMPORTANT:** The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).