	Acadia	2018	to put all promises in writing. Keep this form.
VEHICLE MAKE	MODEL	YEAR	VEHICLE IDENTIFICATION NUMBER (VIN)
WARRANTIES	S FOR THIS VEHICL	E:	
	IS - NO DE Ler does not provide a		<b>NARRANTY</b> Y REPAIRS AFTER SALE.
	ALER WAR	RRANT	(
that fail du explain wa	ring the warranty period. Ask	the dealer for a copy c and the dealer's repair	and <u>100</u> % of the parts for the covered systems of the warranty, and for any documents that obligations. <i>Implied warranties</i> under your
SYSTEMS COVERED:		DURATION:	
ENGINE		1,000 miles	
TRANSMISSION		1,000 miles	
POWER STEERING		1,000 miles	
AIR CONDITIONING		1,000 miles	
Wearable parts such as br	akes, tires, or alignments ARE NOT W	arrantied	
NON-DEALER	WARRANTIES FOR	THIS VEHICLE	:
MANUFACTUR		PLIES. The manufactur	rer's original warranty has not expired on some
—	ER'S USED VEHICLE WARR		
OTHER USED \	VEHICLE WARRANTY APPLI	IES.	
Ask the dealer for a obligations.	copy of the warranty docume	nt and an explanation c	of warranty coverage, exclusions, and repair
coverage, dedu		If you buy a service cor	le for an extra charge. Ask for details about ntract within 90 days of your purchase of this litional rights.
ASK THE DEALER	R IF YOUR MECHANIC CAI	N INSPECT THE VEH	IICLE ON OR OFF THE LOT.
how to obtain a veh	nicle history report, visit ftc.g	ov/usedcars. To chec	<b>SAFETY RECALLS.</b> For information on k for open safety recalls, visit safercar.gov. make the best use of the resources on
	for important additional i	nformation. including	g a list of major defects that may occur in
used motor vehicl			

Here is a list of some major defects that may occur in used vehicles.

#### Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

#### Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

#### Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

#### Cooling System

Leakage including radiator Improperly functioning water pump

#### Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

#### Fuel System

## Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

#### Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags** 

#### Steering System

Too much free play at steering wheel (DOT specs.) Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

#### Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning improperly

#### Tires

Tread depth less than 2/32 inch Sizes mismatched

#### Visible damage

- Wheels
- Visible cracks, damage or repairs Mounting bolts loose or missing

#### Exhaust System

Leakage Catalytic Converter

## DEALER NAME

<u>Chacon Autos, Ltd.</u>

# 1400 SE. Military Dr, San Antonio, TX 78214

TELEPHONE

## chaconinfo@chaconautos.com

210-922-4000 FOR COMPLAINTS AFTER SALE, CONTACT:

# Contact service department at 210-922-4000

**IMPORTANT:** The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).