VEHICLE MAKE MODEL	2020	1N4BL4BV7LC257763
WARRANTIES FOR THIS VEHICL	YEAR E:	VEHICLE IDENTIFICATION NUMBER (VIN)
AS IS - NO DE THE DEALER DOES NOT PROVIDE A		
DEALER WAF	RRANT	(
that fail during the warranty period. Ask	the dealer for a copy c and the dealer's repair	nd <u>100</u> % of the parts for the covered systems of the warranty, and for any documents that obligations. <i>Implied warranties</i> under your
SYSTEMS COVERED:	DURATIO	N:
ENGINE	1,000 mil	es
TRANSMISSION	1,000 mil	es
POWER STEERING	1,000 mil	es
AIR CONDITIONING	1,000 mil	es
Wearable parts such as brakes, tires, or alignments ARE NOT W	arrantied	
NON-DEALER WARRANTIES FOR	THIS VEHICLE	:
components of the vehicle.		rer's original warranty has not expired on some
OTHER USED VEHICLE WARRANTY APPLI Ask the dealer for a copy of the warranty documer obligations.		of warranty coverage, exclusions, and repair
SERVICE CONTRACT. A service contract or coverage, deductible, price, and exclusions. I vehicle, <i>implied warranties</i> under your state's	f you buy a service cor	ntract within 90 days of your purchase of this
ASK THE DEALER IF YOUR MECHANIC CAN	N INSPECT THE VEH	IICLE ON OR OFF THE LOT.
<b>OBTAIN A VEHICLE HISTORY REPORT AND</b> how to obtain a vehicle history report, visit ftc.g You will need the vehicle identification number these sites.	CHECK FOR OPEN ov/usedcars. To chec	SAFETY RECALLS. For information on the for open safety recalls, visit safercar.gov.
SEE OTHER SIDE for important additional ir used motor vehicles.	nformation, including	g a list of major defects that may occur in

Here is a list of some major defects that may occur in used vehicles.

#### Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

### Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

## Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

### Cooling System

Leakage including radiator Improperly functioning water pump

### Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

#### Fuel System

Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

### Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags** 

# Steering System

Too much free play at steering wheel (DOT specs.) Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

### Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning

#### Tires

Tread depth less than 2/32 inch Sizes mismatched

# Visible damage

improperly

- Wheels
- Visible cracks, damage or repairs Mounting bolts loose or missing

# Exhaust System

Leakage Catalytic Converter

# DEALER NAME

<u>Chacon Autos, Ltd.</u>

# 510 E FM 1960 Rd, Houston, TX 77073

TELEPHONE

# chaconinfo@chaconautos.com

281-742-2700 FOR COMPLAINTS AFTER SALE, CONTACT:

# Contact service department at 281-742-2700

**IMPORTANT:** The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).