-	-		to put all promises in writing. Keep this form.	
Kia	Rio	2021	3KPA24AD3ME366300	
VEHICLE MAKE	FOR THIS VEHIC	YEAR	VEHICLE IDENTIFICATION NUMBER (VIN)	
	S-NOD	EALER	NARRANTY	
			Y REPAIRS AFTER SALE.	
			/	
	LER WA	RRANI		
	RANTY.			
that fail duri explain warr	ng the warranty period. A	sk the dealer for a copy os, and the dealer's repair	and <u>100</u> % of the parts for the covered systems of the warranty, and for any documents that obligations. <i>Implied warranties</i> under your	
SYSTEMS COVERE	ED:	DURATIO	N:	
ENGINE		1,000 mil	1,000 miles	
TRANSMISSION		1,000 mil	1,000 miles	
POWER STEERING		1,000 miles		
AIR CONDITIONING		1,000 miles		
Wearable parts such as brai	kes, tires, or alignments ARE NO	T Warrantied		
NON-DEALER W	VARRANTIES FO	R THIS VEHICLE	:	
MANUFACTURE components of th		PPLIES. The manufactu	rer's original warranty has not expired on some	
MANUFACTURE	R'S USED VEHICLE WAI	RRANTY APPLIES.		
OTHER USED VI	EHICLE WARRANTY APP	PLIES.		
Ask the dealer for a cobligations.	opy of the warranty docur	ment and an explanation of	of warranty coverage, exclusions, and repair	
coverage, deduct		s. If you buy a service cor	le for an extra charge. Ask for details about ntract within 90 days of your purchase of this litional rights.	
ASK THE DEALER	IF YOUR MECHANIC C	AN INSPECT THE VEH	IICLE ON OR OFF THE LOT.	
how to obtain a vehi	cle history report, visit fto	c.gov/usedcars. To chec	SAFETY RECALLS. For information on ck for open safety recalls, visit safercar.gov. The make the best use of the resources on	
SEE OTHER SIDE f		l information, including	g a list of major defects that may occur in	

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator Improperly functioning water pump

Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags**

Steering System

Too much free play at steering wheel (DOT specs.) Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning

Tires

Tread depth less than 2/32 inch Sizes mismatched

Visible damage

improperly

- Wheels
- Visible cracks, damage or repairs Mounting bolts loose or missing

Exhaust System

Leakage Catalytic Converter

DEALER NAME

<u>Chacon Autos, Ltd.</u>

510 E FM 1960 Rd, Houston, TX 77073

TELEPHONE

chaconinfo@chaconautos.com

281-742-2700 FOR COMPLAINTS AFTER SALE, CONTACT:

Contact service department at 281-742-2700

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).