-	-		to put all promises in writing. Keep this form.	
VEHICLE MAKE	Rio	2020 YEAR	3KPA24AD6LE336187 VEHICLE IDENTIFICATION NUMBER (VIN)	
	FOR THIS VEHIC		VEHICLE IDENTIFICATION NUMBER (VIII)	
	S-NOD	EALER V	NARRANTY	
			Y REPAIRS AFTER SALE.	
		RRANT	(	
	RANTY.			
	ARRANTY. The dealer wil	l pay <u>100</u> % of the labor a	and <u>100</u> % of the parts for the covered systems	
that fail duri	ng the warranty period. A	sk the dealer for a copy of	of the warranty, and for any documents that obligations. <i>Implied warranties</i> under your	
•	may give you additional rig		obligations. Implied warranties under your	
SYSTEMS COVER	ED:	DURATIO	N:	
ENGINE		_1,000 mil	1,000 miles	
TRANSMISSION		1,000 mil	1,000 miles	
POWER STEERING		<u>1,000 mil</u>	1,000 miles	
AIR CONDITIONI	NG	1,000 mil	es	
	kes, tires, or alignments ARE NO			
NON-DEALER V	VARRANTIES FO	R THIS VEHICLE		
MANUFACTURE components of th		PPLIES. The manufactu	rer's original warranty has not expired on some	
	R'S USED VEHICLE WAI	RRANTY APPLIES.		
	EHICLE WARRANTY API	PLIES.		
			of warranty coverage, exclusions, and repair	
obligations.				
			le for an extra charge. Ask for details about	
	tible, price, and exclusions varranties under your state		ntract within 90 days of your purchase of this ditional rights.	
· •	,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
ASK THE DEALER	IF YOUR MECHANIC C	AN INSPECT THE VEH	IICLE ON OR OFF THE LOT.	
			SAFETY RECALLS. For information on	
			ck for open safety recalls, visit safercar.gov. I make the best use of the resources on	
	for important additiona	l information, including	g a list of major defects that may occur in	

Here is a list of some major defects that may occur in used vehicles.

#### Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

#### Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

### Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

#### Cooling System

Leakage including radiator Improperly functioning water pump

#### Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

#### Fuel System

## Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

### Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags** 

# (DOT specs.)

Steering System

Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

Too much free play at steering wheel

### Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning

#### Tires

Tread depth less than 2/32 inch Sizes mismatched

#### Visible damage

improperly

Wheels

Visible cracks, damage or repairs Mounting bolts loose or missing

### Exhaust System

Leakage Catalytic Converter

## DEALER NAME

<u>Chacon Autos, Ltd.</u>

# 3315 E Pioneer Pkwy, Arlington, TX 76010

TELEPHONE

chaconinfo@chaconautos.com

## 214-826-6000 FOR COMPLAINTS AFTER SALE, CONTACT:

# Contact service department at 214-826-6000

**IMPORTANT:** The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).