			p put all promises in writing. Keep this form.
Mitsubishi	Outlander Sport		JA4APUAU9MU033046
		YEAR	VEHICLE IDENTIFICATION NUMBER (VIN)
WARRANTIES FOR	THIS VEHICLE:		
A3 I3 -	NU DEA		VARRANTY
		RANTY FOR ANY	REPAIRS AFTER SALE.
		RANTY	•
FULL WARRANTY.			
that fail during the wa explain warranty cov	arranty period. Ask the d	ealer for a copy of	d <u>100</u> % of the parts for the covered systems the warranty, and for any documents that obligations. <i>Implied warranties</i> under your
SYSTEMS COVERED:		DURATION	1:
ENGINE		1,000 miles	
TRANSMISSION		1,000 miles	
POWER STEERING		1,000 miles	
AIR CONDITIONING		1,000 miles	
Wearable parts such as brakes, tires, o	r alignments ARE NOT Warrantie	ed	
NON-DEALER WARR	ANTIES FOR THI	S VEHICLE:	
MANUFACTURER'S WAF		. The manufacture	er's original warranty has not expired on some
MANUFACTURER'S USE	D VEHICLE WARRANTY	APPLIES.	
OTHER USED VEHICLE	WARRANTY APPLIES.		
Ask the dealer for a copy of th obligations.	e warranty document and	l an explanation of	warranty coverage, exclusions, and repair
	e, and exclusions. If you	buy a service cont	e for an extra charge. Ask for details about tract within 90 days of your purchase of this tional rights.
ASK THE DEALER IF YOU	R MECHANIC CAN INS	PECT THE VEHI	CLE ON OR OFF THE LOT.
OBTAIN A VEHICLE HISTO how to obtain a vehicle histo	RY REPORT AND CHE ry report, visit ftc.gov/us	CK FOR OPEN S edcars. To check	SAFETY RECALLS. For information on (for open safety recalls, visit safercar.gov. make the best use of the resources on
these sites.			
these sites.	rtant additional inform	ation, including	a list of major defects that may occur in

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator Improperly functioning water pump

Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags**

Steering System

Too much free play at steering wheel (DOT specs.) Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning

Tires

Tread depth less than 2/32 inch Sizes mismatched

Visible damage

improperly

- Wheels
- Visible cracks, damage or repairs Mounting bolts loose or missing

Exhaust System

Leakage Catalytic Converter

DEALER NAME

<u>Chacon Autos, Ltd.</u>

510 E FM 1960 Rd, Houston, TX 77073

TELEPHONE

chaconinfo@chaconautos.com

281-742-2700 FOR COMPLAINTS AFTER SALE, CONTACT:

Contact service department at 281-742-2700

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).