	ANI: Spoken pror			put all promises in writing. Keep this form.
GMC		Yukon	2019	1GKS1DKC1KR386919
		MODEL R THIS VEHICL	YEAR	VEHICLE IDENTIFICATION NUMBER (VIN)
WAR			.⊑.	
\square	AS IS			VARRANTY
		_		REPAIRS AFTER SALE.
	DEAL	ER WAI	RRANTY	•
	FULL WARRANT	<i>(</i> .		
				id% of the parts for the covered systems
	that fail during the explain warranty c	warranty period. Ask	the dealer for a copy of and the dealer's repair c	the warranty, and for any documents that bligations. <i>Implied warranties</i> under your
SYSTEMS COVERED:		DURATION:		
			THIS VEHICLE:	pr's original warranty has not expired on some
		ARRANTY STILL API		er's original warranty has not expired on some
MAN com	IUFACTURER'S W ponents of the vehi	ARRANTY STILL API	PLIES. The manufacture	er's original warranty has not expired on some
MAN com	IUFACTURER'S W ponents of the vehi IUFACTURER'S U	ARRANTY STILL API	PLIES. The manufacture RANTY APPLIES.	er's original warranty has not expired on some
MAN com MAN	IUFACTURER'S W ponents of the vehi IUFACTURER'S U ER USED VEHICL dealer for a copy of	ARRANTY STILL API cle. SED VEHICLE WARF E WARRANTY APPL	PLIES. The manufacture RANTY APPLIES. IES.	er's original warranty has not expired on some
MAN com MAN OTH Ask the obligatio	IUFACTURER'S W ponents of the vehi- IUFACTURER'S U ER USED VEHICL dealer for a copy of ns.	ARRANTY STILL API cle. SED VEHICLE WARF E WARRANTY APPL the warranty docume	PLIES. The manufacture RANTY APPLIES. IES. Int and an explanation of	

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator Improperly functioning water pump

Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags**

Steering System

Too much free play at steering wheel (DOT specs.) Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning improperly

Tires

Tread depth less than 2/32 inch Sizes mismatched

Visible damage

- Wheels
- Visible cracks, damage or repairs Mounting bolts loose or missing

Exhaust System

Leakage Catalytic Converter

DEALER NAME

<u>Chacon Autos, Ltd.</u>

1400 SE. Military Dr, San Antonio, TX 78214

TELEPHONE

chaconinfo@chaconautos.com

210-922-4000 FOR COMPLAINTS AFTER SALE, CONTACT:

Contact service department at 210-922-4000

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).